Spindle Indicator - Mechanic-Analog **I60 – I60F**

Datasheet

- Position indicator with analogue scale (I60) or rather torque support (I60F)
- Measurement of length and angle with gravity principle
- Window of shock-proof polycarbonate
- Available for several hand wheels
- IP-Rating: IP64



llilltec

Messtechnik eK

Mechanical Data

In general								
Material								
Case	Metal or Technopolymer							
Window	shock-proof Polycarbonate							
Indication	analogue dial scale							
Counting Direction	DX clockwise							
	SX anti-clockwise							
Hand								
Big Hand	1:1 ratio with hand wheel							
Little Hand	Transmission Ratio depending on the required shaft revolution							
Transmission Batio	2:1; 4:1; 6:1; 10:1; 12:1; 20:1; 24:1, 30:1; 36:1; 40:1; 60:1;							
	100:1; 120:1; 200:1							
Dial Scale	2-0-2; 0-6; 3-0-3; 0-10; 0-12; 6-0-6; 0-20; 0-24; 0-30; 0-36;							
	18-0-18; 0-40; 0-50; 0-60; 0-80; 0-100							
Operating Temperature	< 80°C							
IP-Rating	IP64							
Optional	oil-filled on request							
160								
Accessories								
Hand Wheel	P70, P100, P100P							
Applications	horizontal or slightly inclined shafts							
I60F (with torque support)								
Accessories								
Hand Wheel	P100FP							
Applications	Shafts with any position							

Willtec Messtechnik ek Eschenweg 4 79232 March-Hugstetten Fon:07665/93465-0 Fax:07665/93465-22 Email: info@willtec.de Internet: www.willtec.de

Measure

Indicate

Control Sensors

Spindle Indicator - Mechanic-Analog **I60 – I60F**

Datasheet



Dimensions

I60





I60F (with torque support)





Ordering Example

Туре		160	-	30	- 1	DX	-	1Z	-	0-30
160										
160F	= with torque support									
Trans	mission Ratio									
30	= 30:1									
For fu	rther Information, see table									
Count	ting Direction									
DX	= clockwise									
SX	= anti clockwise									
Numb	per of Hands									
1Z	= 1 hand									
2Z	= 2 hands									

Dial Scale

0-30 = 0-30 For further Information, see table

Assembling

- Set the drive shaft on the initial adjusting position
- Fix the hand wheel with the pressure screw on the shaft and take care that the instrument is set at the zero (initial) position of the pointers
- Concerning the fixed reaction indicator bear in mind that the lock pin is adjusted on zero at 12 hour.
- Carry out the assembling as described and fix the pin with a bracket.

Willtec Messtechnik ek Eschenweg 4 79232 March-Hugstetten Fon:07665/93465-0 Fax:07665/93465-22 Email: info@willtec.de Internet: www.willtec.de